

Operator Short Instruction



CM 40 with OptiCenter



Gema

Your global partner for high quality powder coating

Switching ON the System

At the Touch Screen

1. System Key to 1




2. Touch the screen




3. Login with User Name and Password


3.1




3.2




3.3 Enter your User Name and push RET after




3.4 Push Password




3.5 Enter the password and push RET




3.6 Push the select Button



3.7 This screen appears



4. Push the Reference Button



Info:


- All Axis start to move to reference position

At the OptiCenter (only waste powder mode)

5. Put the Powder Bag in Cone, add the Lid and put the FP-Lance in, connect the RPP Hose to Waste




6. Choose Waste Powder Mode



Info:

- Ventilation is starting
- The Fresh Powder Pump starts to fill the OptiSpeeder

7. Ready for Production



!!Caution!!


**In Waste Powder Mode you work only with Fresh Powder.
No Powder will be reclaimed!
Change to Recovery Mode after a while!**

At the OptiCenter (recovery powder mode)

8. Put the Powder Bag in Cone, add the Lid and put the FP-Lance in, connect the RPP Hose to Waste



9. Choose Recovery Powder Mode



Info:

- There is NO Ventilation is starting
- The Fresh Powder Pump starts to fill the OptiSpeeder

10. Ready for Production



11. By pushing the timer




You can set the time to recover the powder later




Switching OFF the System

At the Touch Screen


1. Leave the Cleaning Mode by pushing longer the Button




This Screen appears



2. Push again longer the button



This Screen appears




3. System Key to 0



Color change

At the CM40-Panel


1. Push the Hose rinsing Icon



Info:

- Hose rinsing is starting


2. Leave Coating Mode by pushing Broom Icon



Info:

- You can already start with the rough booth cleaning when the main powder from step 2 and 3 disappeared

3. AFTER Step 2 push the Gun blow off Icon





4. Rough Booth cleaning




At the OptiCenter

5. Leave Coating Mode by pushing the Broom Icon



6. Choose the necessary cleaning cycle




7. Clean the Fresh Powder Lance and put it to Parking Position




8. Push the FP Cone under the Speeder



9. Push the Start Icon





Info:

- The empty Speeder sequence is starting
- At the same time the RP Pump is transferring powder from the cyclone
- When this step is done the operator can start to take the paint bag out and clean the bag carrier
- The OptiCenter automatically continues with the remaining steps



10. Now you can start to fine clean the speeder



Info:


- Some powders are very sticky. It is recommended to use a rag instead only the air gun

11. Now you can clean the whole OptiCenter



Remaining Steps


12. Start once more the gun outside cleaning



Info:

- Meanwhile you can start already the booth fine cleaning

13. After gun cleaning is OK, park the gun's outside the booth



14. Clean the Booth seriously



15. Clean the Ducting



16. Clean and remove the Screen




17. Release RP-Hose Cleaning



18. Clean the Cone



19. Clean the Cyclone



20. Put the screen back and close the cyclone



Info:

- It is strongly recommended to clean the cyclone from time to time by Granulate

At the OptiCenter

21. Prepare for the new Color



22. Leave the Cleaning Mode by selecting waste or recovery mode




!!Caution!!


In Waste Powder Mode you work only with Fresh Powder.
No Powder will be recovered!
After a while you will see a reminder
At the CM40 screen

At the CM40-Panel

23. Leave the cleaning mode by pushing Auto Mode



24. Now you are back ready for production



Main Screen

Gema Log in-/ Log out Admin 16.05.2019 12:36

Left Sidebar: Home, Hand, Brush, Menu, Stop

Central Area: Powder Management, After Filter, Access to Gun and Reciprocator Settings, Access to all Programs, Cyclone, Conveyor Speed

Right Panel: DAILY CORRECTION (A: 100%, B: 100%), OBJECT (A: 4 tiny parts white), FUNCTIONS (Axis, Guns, hose clean), Reset Alarm, INFORMATION (SPEED: 2.00 m/min)

Legend:
Yellow: Status active, in Motion
Red: Fault, Malfunction
Hand icon: May be additional Function behind

Gun Settings

Access to Axes Settings Current Recipe Powder Output Total Air High voltage Current Electrode Cleaning

Admin 16.05.2019 12:24

GUN PARAMETER

OBJECT: 4 tiny parts white

1	A	1	40	4.0	60	5	0.1	25	25	
2		2	40	4.0	60	5	0.1	25	25	
3		3	40	4.0	60	5	0.1	25	25	
4		4	40	4.0	60	5	0.1	25	25	
5		5	40	4.0	60	5	0.1	25	25	
6	B	1	40	4.0	60	5	0.1	25	25	
7		2	40	4.0	60	5	0.1	25	25	
8		3	40	4.0	60	5	0.1	25	25	
9		4	40	4.0	60	5	0.1	25	25	
10		5	40	4.0	60	5	0.1	25	25	

Gun ON / OFF before and after the Object

Gun activated

Gun deactivated

Access to all Recipes

Save Changes

Leave Page

Gun spraying

Gun not spraying

INFORMATION

All

Reciprocator Settings

Access to Gun Settings
Current Recipe
Upper Reversing Point
Lower Reversing Point
Current Axis Position
START / STOP (manual Mode only)

Admin
16.05.2019 12:47

AXIS PARAMETER

?

OBJECT: 4 tiny parts white

↑
↓
↑
↔
↔
↔

1	A	Z	27	0	32	14	⏻	20	20	20	
2	A	X	60	0	10	60	⏻	10	10	10	Auto
3	B	Z	27	0	32	14	⏻	2	20	20	
4	B	X	60	0	10	60	⏻	10	10	10	Manu

Axis deactivated

Axis activated

Speed

approx Spray Distance

Access to all Recipes

Save Changes

Leave Page


Start/Stop before and after Object

Automatic X-Axis adjustment

Fix Travel way !! Caution!! Collosion Hazard

All

INFORMATION



Schematic Powder Circuit

